Appendix C - Responsive Maintenance For Gypsy Sites

		0000	TENLANT	N (
Item	PROVIDER	SSDC	TENANT	Notes
Basin, sink or bath plugs	V		Х	
Bath or bath panels	X			
Blockages-rainwater pipe, guttering	X			··· ·· · · · · · · · · ·
Blockages-basin sink or bath	X			If caused by tenant they should be recharged
Blockages-toilet or toilet pipes	Х			
Carbon monoxide alarms	Х			Must be orginally fitted by SSDC
Ceiling repairs	Х			
Central heating	Х			
Chairs/tables			Х	
Coat hooks			Х	
Cooker			Х	
Cooker bulbs			Х	
Curtain batten, rail or pole			Х	
Damage to barriers	Х			
Damage to fencing	Х			
Damage to gates	Х			
Decoration inside			Х	
Decoration outside	Х			
Doors - inside			Х	
Electric consumer unit	Х			
Electric Meter, sockets and wiring	Х			
Extractor fan	Х			
Fences and gates	Х			
Fitted furniture			Х	
Floor covering			Х	
Forced entry required as result of breach of tenancy			Х	
Gas boiler	X			

Gas Fires	Х
Gas leak	Х
Gas pipe work	Х
Gas supply	
Gas test	Х
Gas/electrical applicances not supplied by SSDC	
Glazing	Х
Key replacement	
Kitchen units - door catches, handles and hinges	
Kitchen units - worktop and sinks	Х
Light switches	Х
Lightfittings-bulbs	
Overflow pipes	Х
Pest Control	
Radiators	Х
Rubbish clearance	Х
Satellite dishes	
Sealant to bath, washbasin, sinks and worktops	
Shower and screen	Х
Smoke detector	Х
Steps and handrails	Х
Street lighting	Х
Tap washer replacement	
Taps	Х
Toilet pan and cistern	Х
Toilet seat and lid	
TV aerial	
Water leaks	Х
Water supply	Х
Windows- frames, sills or vents	Х

Must be originally fitted by SSDC

Х

Х

X X

Х

Х

X X

Х

X X